

TALAN SOFTWARE UPDATE INSTRUCTIONS

v3.03

1. Download and extract the TALAN v3.03 software files >> <http://www.reiusa.net/TALAN>
2. Copy extracted files onto USB drive or Compact Flash (CF) card
3. Power off TALAN & insert USB drive or CF card into TALAN
4. Power TALAN on & proceed to Software Verification box below

WARNING: REI recommends connecting the TALAN to AC power during the update process. Without sufficient power there is a risk of the TALAN losing power during the update and rendering the unit inoperable.

SOFTWARE VERIFICATION

- 1) Select **System Scan** from pull-down menu in top-right of the screen
**Note: If System Scan is not listed or TALAN version not shown, proceed to Section 'A' below*
- 2) Under the **TALAN** section, what does the first number listed begin with?
 - (i) A01 – Proceed to **Section 'A'** Below
 - (ii) A02 – Proceed to **Section 'B'** Below
 - (iii) A03 - TALAN is up-to-date. Proceed to **Section 'C'** Below
- 3) Please make note of the full number as this could be used later in the update process

A

- 1) Follow the File Installation Procedure (Orange Box) listed on page 2 using the files below in the order listed
 - (i) **Full_Install_110707.FIX**
 - (ii) **HAST_130403_FE.FIX**
 - (iii) **TALAN20250610.FIX**
- 2) Update has been completed; no further steps are necessary

B

- 1) Select **System Scan** from pull-down menu in top-right of the screen
- 2) Under the **TALAN** section, identify the '**B**' number matching the first characters highlighted in bold below
 - (i) **B.02.00.1112151300** – Proceed to **Section 'C'** below
 - (ii) Any other B number – Proceed to **Section 'D'** below

C

- 3) Using the **File Installation Procedure** (Orange Box) listed on page 2, install the following update file:
 - (i) **TALAN20250610.FIX**
- 4) Update has been completed; no further steps are necessary

D

- 1) Reference the '**A**' version number you documented in the *Software Verification Process* (Blue Box) in the beginning
 - (i) **A02.00** – Proceed to step 2 below
 - (ii) **A02.01 or A02.03** – Proceed to **Section 'C'** Above
- 2) Using the **File Installation Procedure** (Orange Box), install the following update files:
 - (i) **HAST_130403_FE.FIX**
 - (ii) **TALAN20250610.FIX**
- 3) Update has been completed; no further steps are necessary

TALAN SOFTWARE UPDATE INSTRUCTIONS

v3.03

FILE INSTALLATION PROCEDURE

- 1) Press *System tab (F6)* and select *Update*
- 2) Select the correct update file from USB or CF card and press *OK*
- 3) When update is complete, confirm prompt to restart TALAN
 - i. *Note: TALAN may restart multiple times during the update process

TALAN v3.03 Software Version Numbers

TALAN	SMC	AUC	PBX
A03.03.2506101730	A02.02.1304020711	A02.10.1702161515	A02.00.1106290838

The screenshot shows the TALAN 3.0 software interface. On the right, a 'System Scan' panel displays the following information:

- TALAN**: A03.03.2506101730, B02.00.1112151300
- SMC**: A02.02.1304020711, B01.03.0710181515
- AUC**: #00255, A02.10.1702161515, B01.02.0703160830
- PBX**: #71066, A02.00.1106290838, B01.01.0703160837
- Matrix**: #01381
- Audio**: #00894
- RF**: #00697
- NLJD**: #72407
- DMM**: #00915
- Bias**: #70881

The main interface on the left includes a 'Manual Test: Ready' status, a 'DMM' section with 'Tests' set to 'DC Voltage (VDC)', 'Range' set to '440 V', and 'Dwell' set to 'Default'. Below this are 'IDC (A)' and 'IAC (A)' columns with a table of 8 rows. At the bottom, there is a 'Start' button and a 'Shield Earth' checkbox. The bottom navigation bar contains buttons for 'Job', 'Sequence', 'Manual', 'Options', 'Config', and 'System'.

Troubleshooting

If you experience any issues updating your TALAN to version 3.03, please call 1-800-824-3190 for technical support.